SHIMOGA DIVISION.

Dated 10th September 1912.

Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Shimoga Division, up to 5 P.M. of 1st October 1912, for restoring the Benkikere tank, Registered No. 391, Channagiri Taluk. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of March 1914.

- The plans, detailed estimate and conditions may be seen at the Executive Engineer's Office at Shimoga between the hours of 11 A.M. and 5 P.M.
- Tenders should be submitted on printed forms which may be obtained from the Executive Engineer. The tenders should be accompanied by a statement in the form given below, showing the rates at which the different items specified will be executed.
- 4. Each tender must be accompanied by a deposit of Rs. 200 (two hundred), in cash or Government Promissory Notes, as earnest money, and be superscribed "Tender for restoring the Benkikere tank, Register No. 391, Channagiri Taluk," in default of which, tenders will be rejected.
- 5. The final acceptance of any tender will rest with the Superintending Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.
- 6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.
- 7. The name of the successful competitor, whose tender has been accepted, will be posted on the notice board in the Executive Engineer's Office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.
- 8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

Detailed abstract estimate of restoring Benkikere Tank, Register No. 391, Channagiri Taluk

Channagiri Taluk.						
Items of u	vork.				Unit.	Quantity.
Bund R. L. 55:00—			i			
Earthwork to bund			1		C. yd.	10,862
Turfing rear slope		• • •			Sq .	258
Bench mark stones	• • •		· · · · · ·	• • •	Each	2
Grade stones	• • •		• • • •		,,	33
Tank Register No. sto	one		: -+ + +		,,	1
Gauge stone		• • •			,,	1
Date stone			•••		,,	1
Rough stone work, ne	w	• • •	•••		C. yd.	2,551
Royalty for do	•••		•••		,,	2,551
Rough stone work, ol			1		,,	706
Jungle clearing in from	nt and rear	slopes			Lump	sum rupees.
Sluices No. 1 and 2 —						
Examining and repair	ring, etc.				Lump	sum rupees.
Waste weir	O.			ı	-	
Burnt brick in surki	mortar				C. ft.	51
Burnt stone slabs, dre	essed		•••		S. ft.	25
Plastering with surki					Sq.	8.00
Rough stone apron, old and new stone					C. yd.	28
Dismantling, etc					Lump sum rupees.	
Clearing the codi channel				Do		
Breaching bund—						
Earthwork, breaching	and refilli	ng			C. yd.	307
Repairing road—	5	8		***	o. , a.	30.
Gravel over bund	•		1		C vd	1,125
Metal do	•••	***	***	• • •	C. yd.	300
Do do	•••		1	• • •	·,,	$\frac{300}{140}$
	ry road in	the water	-anroad durin	a the	"	140
Forming the temporary road in the water-spread during the execution with earthwork and 6" thickness of gravel and						
consolidation, etc.		C DILLOKI	TODD OF STRACT		As ner r	prevailing rate
constitution, cut.	•••	•••		•••		ad werk.
					101 10	wa worn,

tes

V. R. NIJAGAL, Executive Engineer.